STATE OF WASHINGTON

DEPARTMENT OF FISH & WILDLIFE HABITAT PROGRAM

Salmonid Screening, Habitat Enhancement & Restoration Division (SSHEAR)

OFF-CHANNEL SITE INVENTORY DATA

General Information:

Region: North Coast

Observer(s): Nettnin

River System: Sol Duc

Date: 11/25/96

Site Identifier: S-304R-02

WRIA: 20.0304 F (P)

River Mile Location: 0.9

RB/LB: RB

Local Name: Mud Creek

Trib. to: Gunderson Creek (20.0304)

Legal Description: NE1/4 Sec 30 T29N R13W

County: Clallam

Habitat Type: Valley wall trib

Landowner: () Federal (X) State () County () Other Government (X) Private

Department of Natural Resources Unknown at this time, probably RTOC

Directions to site:

- Head north from Forks on HWY 101 about 3.1 mi. Turn left (west) about 0.1 mi. beyond MP 195 onto D-2000. Proceed west on D-2000 for 1.1 mile to a major stream crossing this is W.F. Gunderson Cr. Proceed to a road junction just past the creek and go to the left. Walk down this road about 0.2 mi. This is S-304R-02.

Site Overview:

- This second order stream drains about 40 - 60 acres of timberland, most of which has been recently clearcut. It sources on the valley wall and flows to Gunderson Creek. It has a moderate to high gradient, flashy flows, and it produces gravel. It has trout and some limited coho rearing potential.

Habitat Information:

Water source: Surface runoff

Intermittent/year-around: Intermittent

Estimated flows (cfs):

Lower end: 1.0 - 2.0

Upper end: Not taken

Date: 12/19/97

0.2 - 0.5

Not taken

Water temperatures:

Lower end: 7.5°C

Upper end: Not taken

Adjacent stream temperature (Gunderson Creek 20.0304): 6.5°C

Other water observations: clear water

Site area measurements: () Indirect () Direct (X) Combination

Widths: Channel- 0.5 - 2.0 m Ponds- NA
Depths: Channel- 5 - 10 cm Ponds- NA

Wetlands- NA Wetlands- NA

Total length surveyed (includes ponds and wetlands): ≈80 m

Total existing habitat area (est.): 160 m²

Spawning area: 4 m² Impounded area: None Other rearing area: 156 m²

Spawning Habitat conditions: () None () Poor (X) Fair () Good () Excellent

Describe spawning habitat:

- The spawning habitat appears to be limited to the reach below the culvert.
- Rubble and larger gravels limit spawning.

Rearing habitat conditions: () None (X) Poor () Fair (X) Good () Excellent

Describe pond and other rearing habitat:

- High gradient, flashy flows and turbid water during rainy periods limit coho rearing to the lower 20 m. Coho may use the lower reach for refuge during high river flows.
- Overall, this stream has better trout habitat.

Describe unaccessible habitat: NA

Describe wetland: (X) None () Bog () Marsh () Scrub-shrub Wetland () Forested Wetland

Flooding potential: (X) Low () Medium () High

Fish Information:

Site entry condition to Gunderson Cr. (20.0304): () Poor (X) Fair () Good

Coho access and use:

Juvenile- (X) Unknown () None () Poor () Fair () Good Adult- (X) Unknown () None () Poor () Fair () Good

- There appears to be unobstructive juvenile access up to the culvert. On low to moderate flows, water filters through the gravel that has built up in the culvert.
- There may have been a redd just above the channel mouth.

Other species access and use: () Chum () Sockeye () Chinook (X) Trout () Res. Trout It is unknown if other species use this system, but it is possible trout do use it.

Habitat Improvements:

Enhancement opportunities:

- Maintain the integrity of the stream.

Additional Comments: See culvert report for culvert data.

Attachments Available:

Contact respective SSHEAR habitat biologist for the following checked items:

(X) Aerials (X) Sketch () Juvenile trapping (X) Culvert Report

() Other references () Spawning surveys () Fishway Report (X) Maps

DOC: S-304R-02

WDFW FISH PASSAGE REPORTING FORM

LEVEL I - Facility/Barrier Identificati		
(1) CHECK ONE:	[] Existing Fishway (includes baffled culverts) [] Man-made Fish Passage Problem	
(2) STREAM: Mud Creek (3) WRIA	RM: 20.0304 F/ 0.9	
(4) TRIBUTARY TO: Gunderson Cree	(5) LEGAL(S,T,R): sec30, T29N, R13W	
(6) LATITUDE/LONGITUDE:		
west on D-2000 for 1.1 mile to a major	CHECK ONE: [] Existing Fishway (includes baffled culverts) [] Man-made Fish Passage Problem STREAM: Mud Creek (3) WRIA#/RM: 20.0304 F/0.9 TRIBUTARY TO: Gunderson Creek (5) LEGAL(S,T,R): sec30, T29N, R13W LATITUDE/LONGITUDE: MILEPOST/ROAD: Id north from Forks on HWY 101 about 3.1 mi. Turn left (west) about 0.1 mi. beyond MP 195 onto D-2000. Proceed to on D-2000 for 1.1 mile to a major stream crossing. This is W.F. Gunderson Cr. Proceed to a road junction just past creek to the left. Walk down this road about 0.2 mi. This is S-304R-02. DESCRIPTION OF FISHWAY, FACILITY: DESCRIPTION OF BARRIER: OWNER: Rayonier Timber Operations Company FISH ACCESS UP TO BARRIER VERIFIED/PRIMARY SPECIES: Yes / coho HABITAT AVAILABLE ABOVE FISHWAY OR BARRIER: IDENTIFIED BY (agency/organization): WDFW - SSHEAR SUBMITTED BY/DATE OBSERVED: Nettnin / 4/8/97 INVENTORY DESCRIPTOR: S-304R-02	
(8) DESCRIPTION OF FISHWAY, FAC		
(9) DESCRIPTION OF BARRIER:		
(10) OWNER: Rayonier Timber Ope		
12) HABITAT AVAILABLE ABOVE FISHWAY OR BARRIER: 13) IDENTIFIED BY (agency/organization): WDFW - SSHEAR		
	(14) SUBMITTED BY/DATE OBSERV	9: Nettnin / 4/8/97
	(15) INVENTORY DESCRIPTOR: S-	4R-02
LEVEL II - Culvert/Barrier Descriptio		
CULVERT:		
(16) TYPE (Indicate number of each)	h •	
(17) LENGTH: 50 ft	[] smooth steel pipe	
(18) DIAMETER: 4 ft	[] CMP - Arch or Ellipse	
(19) WATER DEPTH: 3 in	20) SLOPE: 3.5 ft (21) VELOCITY:	
(22) OUTFALL DROP: No plunge		
DAM: (23) LENGTH:	(24) HEIGHT:	

COMMENTS: Gravel is deposited three quarters the way through the pipe. Low flows filter through the gravel, moderate flows may be enough to pass fish.

DOC: S-304R-02





